## PESOLUTION OF THE WHITE MOUNTAIN APACHE TRIBE OF THE FORT APACHE INDIAN RESERVATION

- WHEREAS, the Tribal Council has received information that the Quintero Bridge and the East Fork Road are in need of maintenance; especially, the Quintero Bridge after floods or storms and that there may exist a potential danger to persons using the bridge unless checked after each storm and flood for stability, and
- WHEREAS, the Tribal Council concludes that the stability of the Quintero Bridge and maintenance of the East Fork Road should be the responsibility of the Bureau of Indian Affairs.
- BE IT RESOLVED by the Tribal Council of the White Mountain Apache Tribe that it hereby requests the Bureau of Indian Affairs to maintain the Quintero Bridge and to check the bridge for stability after floods and storms to ensure its safety for the use of the community peope and; further, that the Bureau of Indian Affairs maintain the East Fork Poad for the benefit of the public.

The foregoing resolution was on August 07, 1985 duly adopted by a vote of 9 for and 0 against by the Tribal Council of the White Mountain Apache Tribe, pursuant to authority vested in it by Article V, Section 1 (i) of the Amended Constitution and By-Laws of the Tribe, ratified by the Tribe June 27, 1958 and approved by the Secretary of the Inteterior on May 29, 1958, pursuant to Section 16 of the Act of June 18, 1934 (48 Stat. 984).

Chairman of the Tribal Council

AUG 16 1985

FORT APACHE INDIAN AGENCY WHITERIVER, ARIZ.

Resolution No. 85-189